

## PART#AXHRP7ME BUCKET MODIFICATION INSTRUCTIONS

### Step#1

Remove existing wire



### Step#5

With razor blade, score the inside left edge of the support bucket



### Step#2

Unscrew the 4-bucket screws



### Step#6

With vise grips, bend back the side panel of support bucket



### Step#3

Remove existing Bucket



### Step#7

Remove the broken side panel of the support bucket



### Step#4

Peel back the leather from the right and left side of the support bucket



### Step#8

Repeat steps 5, 6 and 7 on the right side of the support bucket